

SubSurface
Variability

Acres

0



Tiles not functioning

1



12



46



74



22



4



Total 160

Possible tile breach

Drain tiles functioning

Company:
Farm:
Field:

Crop:
Flight Time: 10:00
Flight Date: 9/4/01

